

No. F.25-305 /EE/DD/2703-04
Government of Tripura
Office of the Executive Engineer
PWD (R&B) Dharmanagar Division
Dharmanagar, North Tripura

Dated 21/07/2026

To
The Head Master
Padmapur H.S.School,
Dharmanagar, North Tripura.

Subject:- Building Safety Certificate for extension of CBSE affiliation certificate of Padmapur H.S.School, Dharmanagar.

Refere :- Letter No.F.4(16) /HM/ PHSS /DMN/2014 Date. 14/07/2026.

Sir,

With reference to the communication received from your end, please find enclosed herewith Building Safety certificate in respect of Padmapur H.S. School, Dharmanagar as prepared by the SDO,PWD(R&B), Dharmanagar, Sub-Division.

This is for favour of your kind information and doing needful from your end please.

Enclo:- Observation Report.

Yours faithfully,

(Er. Siddhartha Sankar Deb)
Executive Engineer
Dharmanagar Division, PWD(R&B)
Dharmanagar, North Tripura

Copy to:-

- 1) The SDO, PWD(R&B), Dharmanagar Sub-Division Dharmanagar, North Tripura for kind information.

Copy Attested

03.09.2026
Amit Kilikdar
Vice Principal
H.O. & DDO
Padmapur H.S. School
Dharmanagar, North Tripura.

Executive Engineer
Dharmanagar Division, PWD(R&B)
Dharmanagar, North Tripura

**PROPORMA FOR THE SAFETY OF SCHOOL BUILDING
PART-1**

(To be filled by the Head of School/ Institute)

1. Name of the school : PADMAPUR H.S. SCHOOL
2. Location : DHARMANAGAR
3. Plot Area : 02.238 Acre (As per records)
4. Building Details : Detailed below

Building Details	Number of Storeys	Year of Construction	Roofing Details	Walling Details	Flooring Details
Building- A1	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- A2	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- A3	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- A4	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- A5	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- A6	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- C	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- B1	01	Data not available	GCI Sheet Roof	125 MM Brickwork	CC Floor
Building- B2	01	Data not available	GCI Sheet Roof	125 MM Brickwork	CC Floor
Building- B3	01	Data not available	GCI Sheet Roof	125 MM Brickwork	CC Floor
Building- K1	01	Data not available	GCI Sheet Roof	125 MM Brickwork	CC Floor
Building- K2	01	Data not available	GCI Sheet Roof	125 MM Brickwork	CC Floor
Building- T1	01	2014	RCC Flat Roof	125 MM Brickwork	CC Floor
Building- T2	01	2015	RCC Flat Roof	125 MM Brickwork	CC Floor
Building -S (Cycle stand)	01	Data not available	GCI Sheet Roof	125 MM Brickwork	CC Floor
Building- N1	01	2021	RCC Flat Roof	125/250 MM Brickwork	CC Floor
Building- O	01	Data not available	GCI Sheet Roof	250 MM Brickwork	CC Floor
Building- N2	02	2025	RCC Flat Roof	250 MM Brickwork	Tiles

5. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given


- a) Name of the Engineer with qualification : Not known
- b) Address of Engineer : Not known
- c) Set of Structural drawings used in the construction, if available : Not Available
- d) Name & address of Architect with qualification : Not Known

6. Whether the building has been constructed for the purpose

- a) School : YES/NO
- b) Residential Purpose and converted for use as a School : YES/NO

7. A detailed drawing indicating dimensions of the rooms along with size and location of doors and windows (Attached)

Signature with Stamp of the seal of the School/ Institute


Amit Kilikdar
 Vice Principal
 H.O. & DDO
 Padmapur H.S. School
 North Tripura.

PART-II
(To be filled by the S.D.E)

- a) I have visited the above mentioned school on dated 15th July 2026 and have visually inspected each & every building from all angles of safety. Building wise observations and necessary recommendations are furnished below:-

Name of Building		Clinical Observation		Recommendation
Building No.	Type of Structure	Plinth Area (in Sqm)	Remarks	
Building- A1	Load Bearing	111.00	Building is in good Condition. Some Petty maintenance to walls and ceilings and roofs is recommended.	
Building- A2	Load Bearing	348.75	Building is in good Condition. Some Petty maintenance to walls and ceilings and roofs is recommended.	
Building- A3	Load Bearing	262.50	Building is in poor Condition. Major maintenance to floors, walls and roof including painting is recommended.	
Building- A4	Load Bearing	348.75	Building is in good Condition. Some Petty maintenance to walls and ceilings and roofs is recommended.	
Building- A5	Load Bearing	122.45	Building is in good Condition. Some Petty maintenance to walls is recommended.	
Building- A6	Load Bearing	191.25	Building is in good Condition. Some Petty maintenance to floors, walls and ceilings and roofs including painting is recommended.	
Building- C	Load Bearing	16.20	Building is in good Condition. Some Petty maintenance to floors, walls and ceilings and roofs including painting is recommended.	
Building- B1	Semi Permanent	11.55	Building is in good Condition. Some Petty maintenance to floors, walls and ceilings and roofs including painting is recommended.	
Building- B2	Semi Permanent	96.25	Building is in good Condition. Some Petty maintenance to floors, walls and ceilings and roofs including painting is recommended.	
Building- B3	Semi Permanent	100.00	Building is in good Condition. Some Petty maintenance to walls and ceilings and roofs is recommended.	
Building- K1	Semi Permanent	21.00	Building is in fair Condition. Petty maintenance including painting is recommended	
Building- K2	Semi Permanent	12.50	Building is in fair Condition. Petty maintenance including painting is recommended	
Building- T1	RCC Framed	9.00	Building is in good Condition.	
Building- T2	RCC Framed	6.00	Building is in good Condition. Some Petty maintenance to walls and ceilings and roofs is recommended.	
Building -S (Cycle stand)	Semi Permanent	139.50	Building is in fair Condition. Petty maintenance including painting is recommended	
Building- N1	RCC Framed	314.50	Building is in good Condition. Some Petty maintenance to floors, walls and ceilings and roofs including painting is recommended.	
Building- O	Masonry	32.50	Building is in good Condition.	
Building- N2	RCC Framed	395.01	Building is in good Condition.	
Plinth Area		Total :	2538.71	Square meters

- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re- obtained after the completion from the undersigned.

- c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) These buildings can be safely occupied for normal use if the minor maintenance is carried out as per the recommendations of the undersigned upto 3 (Three) years (indicate up to which it can be used).

①
16/07/26

16/07/26

Sub Divisional Officer
PWD (R&B) Dharmanagar Sub-Division,
Dharmanagar, North Tripura

03.09.2026
Amit Kilikdar
Vice Principal
H.O. & DDO
Padmapur H.S. School
Dharmanagar, North Tripura.